

**Flood Control Project Maintenance
Levee Inspections**

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including USACE Erosion Survey

Sacramento River Basin

NA0001	Overall LMA Rating	Total LMA Miles				
American River Flood Control District	A	33.24				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Vegetation	0.08		0.08	0.24%		
Encroachments	0.28		0.28	0.84%	1.81	1.90
Animal Control	0.32		0.32	0.96%		
Slope Stability	0.02		0.02	0.06%		
<i>LMA Totals:</i>	0.70	0.00	0.70	2.11%	1.81	1.90
Unit No. 01 Arcade Creek	Overall Unit Rating	Total Unit Miles				
	A	2.10				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Encroachments	0.07		0.07	3.33%	0.09	0.22
Animal Control	0.07		0.07	3.33%		
Slope Stability	0.02		0.02	0.95%		
<i>Unit Totals:</i>	0.16	0.00	0.16	7.62%	0.09	0.22
Unit No. 02 Natomas E Canal	Overall Unit Rating	Total Unit Miles				
	A	3.95				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Encroachments	0.02		0.02	0.51%		
<i>Unit Totals:</i>	0.02	0.00	0.02	0.51%	0.00	0.00
Unit No. 03 American River	Overall Unit Rating	Total Unit Miles				
	A	2.78				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
Unit No. 04 American River	Overall Unit Rating	Total Unit Miles				
	A	10.97				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Vegetation	0.08		0.08	0.73%		
Encroachments	0.16		0.16	1.46%	1.10	1.36
Animal Control	0.20		0.20	1.82%		
<i>Unit Totals:</i>	0.44	0.00	0.44	4.01%	1.10	1.36
Unit No. 05 Sacramento River	Overall Unit Rating	Total Unit Miles				
	A	0.40				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Encroachments	0.01		0.01	2.50%	0.03	
<i>Unit Totals:</i>	0.01	0.00	0.01	2.50%	0.03	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 06 Linda Creek	Overall Unit Rating	Total Unit Miles				
	A	1.30				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

Unit No. 07 Arcade Creek	Overall Unit Rating	Total Unit Miles				
	A	1.92				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Encroachments	0.01		0.01	0.52%	0.07	0.19
Animal Control	0.01		0.01	0.52%		
<i>Unit Totals:</i>	0.02	0.00	0.02	1.04%	0.07	0.19

Unit No. 08 Magpie Creek Diversion	Overall Unit Rating	Total Unit Miles				
	A	1.43				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Encroachments	0.01		0.01	0.70%	0.42	
Animal Control	0.01		0.01	0.70%		
<i>Unit Totals:</i>	0.02	0.00	0.02	1.40%	0.42	0.00

Unit No. 09 American River	Overall Unit Rating	Total Unit Miles				
	A	4.32				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Encroachments					0.09	0.13
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.09	0.13

Unit No. 10 American River	Overall Unit Rating	Total Unit Miles				
	A	3.34				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Encroachments					0.01	
Animal Control	0.01		0.01	0.30%		
<i>Unit Totals:</i>	0.01	0.00	0.01	0.30%	0.01	0.00

Unit No. 11 New Linda Creek	Overall Unit Rating	Total Unit Miles				
	A	0.73				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Animal Control	0.02		0.02	2.74%		
<i>Unit Totals:</i>	0.02	0.00	0.02	2.74%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Fall 2009 Levee Inspection Results

American River Flood Control District

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			A	

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2009 Levee Inspection Results

American River Flood Control District

Waterway			Bank	Unit Miles
Unit No. 01 Arcade Creek			Left	2.10
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/17/2009		10/2/2009	
DWR Inspector	Clay Thomas		John Paasch	
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Arcade Creek				Left	2.10	10/27/2009 10/27/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.04	0.04	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.619607 ° -121.467030 °	38.619607 ° -121.467030 °	48 Y
2	0.10	0.10	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows. Inspector Comments: Rodent hole near abandoned sofa.	38.620100 ° -121.466118 °	38.620100 ° -121.466118 °	49 Y
3	0.19	0.19	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.620841 ° -121.464752 °	38.620841 ° -121.464752 °	50 Y
4	0.22	0.22	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.621088 ° -121.464297 °	38.621088 ° -121.464297 °	47 Y
5	0.46	0.46	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows. Inspector Comments: Several active rodent holes on levee slope	38.623058 ° -121.460649 °	38.623058 ° -121.460649 °	46 Y
6	0.57	0.57	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows. Inspector Comments: Several active rodent holes on levee slope	38.623659 ° -121.458786 °	38.623659 ° -121.458786 °	45 Y
7	0.70	0.70	Earthen Levee	Encroachments	LS	M	Prunings Inspector Comments: Tree prunings on levee slope.	38.623766 ° -121.456399 °	38.623766 ° -121.456399 °	44 Y
8	0.72	0.72	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence within 10-ft of levee toe.	38.623824 ° -121.456037 °	38.623824 ° -121.456037 °	43 Y
9	0.78	0.78	Earthen Levee	Trim / Thin Trees	LS	C	Trim trees to at least five feet above ground level.	38.624010 ° -121.455138 °	38.624010 ° -121.455138 °	25
10	0.81	0.81	Earthen Levee	Slope Stability	LS	M	Repair the levee slope damaged by foot traffic and prevent access where possible.	38.624305 ° -121.454506 °	38.624305 ° -121.454506 °	42 Y
11	1.05	1.05	Earthen Levee	Encroachments	LS	M	Debris Inspector Comments: Fence posts and footings left along levee toe.	38.625048 ° -121.450389 °	38.625048 ° -121.450389 °	41 Y
12	1.09	1.09	Earthen Levee	Encroachments	LS	M	Debris Inspector Comments: Concrete rubble left along levee toe.	38.624943 ° -121.449663 °	38.624943 ° -121.449663 °	40
13	1.14	1.14	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Dog-eared wooden fence is built against the levee slope. Fence is partially fallen near swimming pool.	38.624800 ° -121.448808 °	38.624800 ° -121.448808 °	24 Y
14	1.16	1.16	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Dog-eared wooden fence and chain link fence is built against the levee slope.	38.624832 ° -121.448607 °	38.624832 ° -121.448607 °	23

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Arcade Creek				Left	2.10	10/27/2009 10/27/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
15	1.17	1.17	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Dog-eared wooden fence is built against the levee slope.	38.624850 ° -121.448428 °	38.624850 ° -121.448428 °	22
16	1.18	1.18	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Dog-eared wooden fence is built against the levee slope.	38.624877 ° -121.448248 °	38.624877 ° -121.448248 °	21
17	1.19	1.19	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Dog-eared wooden fence is built against the levee slope.	38.624900 ° -121.448037 °	38.624900 ° -121.448037 °	20 Y
18	1.26	1.26	Earthen Levee	Animal Control	CR	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.625376 ° -121.446659 °	38.625376 ° -121.446659 °	39 Y
19	1.26	1.26	Earthen Levee	Encroachments	LS	CO	Buildings Inspector Comments: Cement block building within 10-ft of toe.	38.625300 ° -121.446767 °	38.625300 ° -121.446767 °	18 Y
20	1.35	1.35	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence	38.625827 ° -121.445395 °	38.625827 ° -121.445395 °	17
21	1.37	1.37	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence	38.626000 ° -121.444978 °	38.626000 ° -121.444978 °	16
22	1.38	1.38	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence with vine on levee slope.	38.626048 ° -121.444785 °	38.626048 ° -121.444785 °	15 Y
23	1.39	1.39	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence	38.626085 ° -121.444580 °	38.626085 ° -121.444580 °	14
24	1.40	1.40	Earthen Levee	Encroachments	LS	PO	Buildings Inspector Comments: Small wooden storage shed and firewood are placed along chain link fence within 10-ft of levee toe.	38.626210 ° -121.444320 °	38.626210 ° -121.444320 °	38 Y
25	1.41	1.41	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden fence with barbed wire is built within 10-ft of levee toe.	38.626155 ° -121.444250 °	38.626155 ° -121.444250 °	13
26	1.42	1.42	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Dog-eared wooden fence is built near the levee slope.	38.626212 ° -121.444082 °	38.626212 ° -121.444082 °	12 Y
27	1.43	1.43	Earthen Levee	Slope Stability	LS	M	Repair slope instability. Inspector Comments: 12" DIA hole on hinge point	38.626419 ° -121.443842 °	38.626419 ° -121.443842 °	37 Y
28	1.43	1.43	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Brush near apartment mattresses.	38.626325 ° -121.443928 °	38.626325 ° -121.443928 °	11 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway					Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Arcade Creek					Left	2.10	10/27/2009 10/27/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	
29	1.50	1.50	Earthen Levee	Encroachments	LS	M	Tree or limb Inspector Comments: Downed tree limb on levee slope.	38.627098 ° -121.442889 °	38.627098 ° -121.442889 °	36 Y
30	1.54	1.54	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Stump: Bushes and trees along chain link fence block access and visibility.	38.627281 ° -121.442203 °	38.627281 ° -121.442203 °	35 Y
31	1.55	1.55	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Bushes and trees obstruct visibility.	38.627267 ° -121.442138 °	38.627267 ° -121.442138 °	10 Y
32	1.82	1.82	Earthen Levee	Encroachments	LS	CO	Buildings Inspector Comments: Wooden animal pen is built against levee slope.	38.627915 ° -121.437246 °	38.627915 ° -121.437246 °	33 Y
33	1.83	1.83	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Dog-eared wooden fence is built near the levee slope and has partially fallen. Bushes are overgrown.	38.627880 ° -121.437368 °	38.627880 ° -121.437368 °	9 Y
34	1.85	1.85	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Grape vine and brush obstruct visibility.	38.627893 ° -121.436694 °	38.627893 ° -121.436694 °	32 Y
35	1.87	1.87	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Ivy, trees and other landscaping growing on a wooden privacy fence are obstructing visibility.	38.627827 ° -121.436633 °	38.627827 ° -121.436633 °	8 Y
36	1.88	1.88	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Metal sided shelter, blackberries and cherry trees are obstructive.	38.627837 ° -121.436393 °	38.627837 ° -121.436393 °	7 Y
37	1.91	1.91	Earthen Levee	Encroachments	LS	M	Firewood Inspector Comments: Wood and other material is piled within 10-ft of levee toe.	38.627752 ° -121.435608 °	38.627752 ° -121.435608 °	31 Y
38	1.92	1.92	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Dog-eared wooden fence is built within 10-ft of the levee slope.	38.627725 ° -121.435715 °	38.627725 ° -121.435715 °	6
39	1.93	1.93	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Dog-eared wooden fence is built against the levee slope.	38.627680 ° -121.435555 °	38.627680 ° -121.435555 °	5
40	1.94	1.94	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden fence and landscaping completely block visibility.	38.627640 ° -121.435378 °	38.627640 ° -121.435378 °	4
41	1.95	1.95	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Dog-eared wooden fence is built against the levee slope.	38.627595 ° -121.435218 °	38.627595 ° -121.435218 °	3 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Arcade Creek				Left	2.10	10/27/2009 10/27/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	
42	1.95	1.95	Earthen Levee	Encroachments	LS	CO	Buildings Inspector Comments: Concrete pad and wooden frame structure is being built within 10-ft of levee toe.	38.627589 ° -121.434900 °	38.627589 ° -121.434900 °	30 Y
43	1.99	1.99	Earthen Levee	Encroachments	LS	M	Material Inspector Comments: Cement blocks are stacked on concrete pad along levee toe.	38.627377 ° -121.434383 °	38.627377 ° -121.434383 °	2 Y
44	2.00	2.00	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Vine growing on fence and slope blocks visibility.	38.627318 ° -121.434208 °	38.627318 ° -121.434208 °	1 Y
45	2.03	2.03	Earthen Levee	Encroachments	LS	CO	Buildings Inspector Comments: Two-story home foundation is within 10-ft of levee toe. Chain link fence is built on levee toe.	38.627279 ° -121.433482 °	38.627279 ° -121.433482 °	29 Y
46	2.05	2.05	Earthen Levee	Encroachments	LS	CO	Buildings Inspector Comments: Large wooden building behind corrugated metal covered fence is within 10-ft of levee toe.	38.627249 ° -121.433115 °	38.627249 ° -121.433115 °	28 Y
47	2.07	2.07	Earthen Levee	Encroachments	LS	PO	Buildings Inspector Comments: Pre-fab storage shed is within 10-ft of landside toe.	38.627237 ° -121.432746 °	38.627237 ° -121.432746 °	27 Y
48	2.08	2.08	Earthen Levee	Encroachments	LS	M	Prunings Inspector Comments: Tree limbs piled on levee slope against field fence.	38.627231 ° -121.432562 °	38.627231 ° -121.432562 °	26 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Arcade Creek	Left	2.10	10/27/2009 10/27/2009	John Paasch

Levee Mile Report Line	1
Start Levee Mile	0.04
End Levee Mile	0.04
Location	Land Side
Category	Earthen Levee
Item	Animal Control

Photo of active rodent hole near LM 0.04

jpaasch_20091029_115.jpg



Levee Mile Report Line	2
Start Levee Mile	0.10
End Levee Mile	0.10
Location	Land Side
Category	Earthen Levee
Item	Animal Control

Photo of active rodent hole near LM 0.10

jpaasch_20091029_116.jpg



Levee Mile Report Line	3
Start Levee Mile	0.19
End Levee Mile	0.19
Location	Land Side
Category	Earthen Levee
Item	Animal Control

Photo of active rodent hole near LM 0.19

jpaasch_20091029_117.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Arcade Creek	Left	2.10	10/27/2009 10/27/2009	John Paasch

Levee Mile Report Line	4
Start Levee Mile	0.22
End Levee Mile	0.22
Location	Land Side
Category	Earthen Levee
Item	Animal Control

Photo of active rodent hole near LM 0.22.

jpaasch_20091029_114.jpg



Levee Mile Report Line	5
Start Levee Mile	0.46
End Levee Mile	0.46
Location	Land Side
Category	Earthen Levee
Item	Animal Control

Photo of active rodent holes near LM 0.46.

jpaasch_20091029_113.jpg



Levee Mile Report Line	6
Start Levee Mile	0.57
End Levee Mile	0.57
Location	Land Side
Category	Earthen Levee
Item	Animal Control

Photo of rodent holes near LM 0.57.

jpaasch_20091029_112.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Arcade Creek	Left	2.10	10/27/2009 10/27/2009	John Paasch

Levee Mile Report Line	7
Start Levee Mile	0.70
End Levee Mile	0.70
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Photo of prunings left on levee slope.

jpaasch_20091029_109.jpg



Levee Mile Report Line	8
Start Levee Mile	0.72
End Levee Mile	0.72
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Wooden fence within 10-ft of levee toe obstructs visibility.

jpaasch_20091029_110.jpg



Levee Mile Report Line	10
Start Levee Mile	0.81
End Levee Mile	0.81
Location	Land Side
Category	Earthen Levee
Item	Slope Stability

Photo of levee slope damage caused by foot traffic.

jpaasch_20091029_111.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Arcade Creek	Left	2.10	10/27/2009 10/27/2009	John Paasch

Levee Mile Report Line	11
Start Levee Mile	1.05
End Levee Mile	1.05
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Photo of fence post left at levee toe.

jpaasch_20091029_108.jpg



Levee Mile Report Line	13
Start Levee Mile	1.14
End Levee Mile	1.14
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Photo of damaged wooden fence.

jpaasch_20091029_107.jpg



Levee Mile Report Line	17
Start Levee Mile	1.19
End Levee Mile	1.19
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Photo of solid fences built against the levee slope.

jpaasch_20091029_106.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Arcade Creek	Left	2.10	10/27/2009 10/27/2009	John Paasch

Levee Mile Report Line	18
Start Levee Mile	1.26
End Levee Mile	1.26
Location	Crown
Category	Earthen Levee
Item	Animal Control

Photo of animal burrow on crown at landside hinge point.

jpaasch_20091029_105.jpg



Levee Mile Report Line	19
Start Levee Mile	1.26
End Levee Mile	1.26
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Photo of buildings and fence near levee toe.

jpaasch_20091029_102.jpg



Levee Mile Report Line	22
Start Levee Mile	1.38
End Levee Mile	1.38
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Wooden and wire fence are within 10-ft of levee toe.

jpaasch_20091029_103.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Arcade Creek	Left	2.10	10/27/2009 10/27/2009	John Paasch

Levee Mile Report Line	24
Start Levee Mile	1.40
End Levee Mile	1.40
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Photo of small wooden building behind dense vegetation near levee slope.

jpaasch_20091029_104.jpg



Levee Mile Report Line	26
Start Levee Mile	1.42
End Levee Mile	1.42
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Photo of wooden fence built near levee slope.

jpaasch_20091029_101.jpg



Levee Mile Report Line	27
Start Levee Mile	1.43
End Levee Mile	1.43
Location	Land Side
Category	Earthen Levee
Item	Slope Stability

Photo of hole on landside hinge point.

jpaasch_20091029_100.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Arcade Creek	Left	2.10	10/27/2009 10/27/2009	John Paasch

Levee Mile Report Line	28
Start Levee Mile	1.43
End Levee Mile	1.43
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Brush completely blocks visibility and access to the levee slope and toe.

jpaasch_20091029_99.jpg



Levee Mile Report Line	29
Start Levee Mile	1.50
End Levee Mile	1.50
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Photo of downed tree limb on levee slope.

jpaasch_20091029_98.jpg



Levee Mile Report Line	30
Start Levee Mile	1.54
End Levee Mile	1.54
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Photo of vegetation obstructing visibility near levee slope.

jpaasch_20091029_96.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Arcade Creek	Left	2.10	10/27/2009 10/27/2009	John Paasch

Levee Mile Report Line	31
Start Levee Mile	1.55
End Levee Mile	1.55
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Photo of Photinias and other plants planted near levee toe.

jpaasch_20091029_97.jpg



Levee Mile Report Line	32
Start Levee Mile	1.82
End Levee Mile	1.82
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Photo of wooden animal shelter and vegetation near levee slope.

jpaasch_20091029_95.jpg



Levee Mile Report Line	33
Start Levee Mile	1.83
End Levee Mile	1.83
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Photo of partially obstructive vegetation and fence.

jpaasch_20091029_94.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Arcade Creek	Left	2.10	10/27/2009 10/27/2009	John Paasch

Levee Mile Report Line	34
Start Levee Mile	1.85
End Levee Mile	1.85
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Grapevine and brush growing on fence near the levee toe. Visibility and access are obstructed.

jpaasch_20091029_93.jpg



Levee Mile Report Line	35
Start Levee Mile	1.87
End Levee Mile	1.87
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Photo of vegetation growing on wooden fence.

jpaasch_20091029_92.jpg



Levee Mile Report Line	36
Start Levee Mile	1.88
End Levee Mile	1.88
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Metal sided shed covered with brush is built near levee toe.

jpaasch_20091029_91.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Arcade Creek	Left	2.10	10/27/2009 10/27/2009	John Paasch

Levee Mile Report Line	37
Start Levee Mile	1.91
End Levee Mile	1.91
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Wood and debris is piled near levee toe.

jpaasch_20091029_90.jpg



Levee Mile Report Line	41
Start Levee Mile	1.95
End Levee Mile	1.95
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Wooden fence built on levee slope.

jpaasch_20091029_89.jpg



Levee Mile Report Line	42
Start Levee Mile	1.95
End Levee Mile	1.95
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Photo of building being built near levee toe.

jpaasch_20091029_88.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Arcade Creek	Left	2.10	10/27/2009 10/27/2009	John Paasch

Levee Mile Report Line	43
Start Levee Mile	1.99
End Levee Mile	1.99
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Photo of cement blocks placed on concrete pad at levee toe.

jpaasch_20091029_87.jpg



Levee Mile Report Line	44
Start Levee Mile	2.00
End Levee Mile	2.00
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Photo of vines on fence. Visibility and access are limited.

jpaasch_20091029_86.jpg



Levee Mile Report Line	46
Start Levee Mile	2.05
End Levee Mile	2.05
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Photo of building within 10-ft of levee toe. Fence is partially obstructive.

jpaasch_20091029_85.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Arcade Creek	Left	2.10	10/27/2009 10/27/2009	John Paasch

Levee Mile Report Line	47
Start Levee Mile	2.07
End Levee Mile	2.07
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Photo of building within 10-ft of levee toe.

jpaasch_20091029_84.jpg



Levee Mile Report Line	48
Start Levee Mile	2.08
End Levee Mile	2.08
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Photo of tree limbs against fence on levee slope.

jpaasch_20091029_83.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2009 Levee Inspection Results

American River Flood Control District

Waterway			Bank	Unit Miles
Unit No. 02 Natomas E Canal			Left	3.95
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/17/2009		10/2/2009	
DWR Inspector	Clay Thomas		John Paasch	
Accompanied By			Ilene Wellman-Barbree	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Natomas E Canal				Left	3.95	10/02/2009 10/02/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	3.38	3.38	Earthen Levee	Encroachments	LS	M	Debris Inspector Comments: Downed pole and crossarms along levee toe.	38.649459 ° -121.473420 °	38.649459 ° -121.473420 °	3
2	3.59	3.59	Earthen Levee	Encroachments	LS	M	Debris Inspector Comments: Downed pole and crossarms on levee slope.	38.652377 ° -121.473972 °	38.652377 ° -121.473972 °	2
3	3.63	3.63	Earthen Levee	Slope Stability	LS	A	Inspector Comments: Minor erosion on landside slope should be monitored and possibly repaired.	38.652940 ° -121.474075 °	38.652940 ° -121.474075 °	1 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Natomas E Canal	Left	3.95	10/02/2009 10/02/2009	John Paasch

Levee Mile Report Line	3
Start Levee Mile	3.63
End Levee Mile	3.63
Location	
Category	Earthen Levee
Item	Slope Stability

Photo showing eroded slope.

jpaasch_20091002_3.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2009 Levee Inspection Results

American River Flood Control District

Waterway			Bank	Unit Miles
Unit No. 03 American River			Right	2.78

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/17/2009		10/2/2009	
DWR Inspector	Clay Thomas		John Paasch	
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 American River	Right	2.78	10/07/2009 10/07/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	
1	2.76	2.76	Earthen Levee	Animal Control	LS	C	Exterminate rodents and backfill and compact or grout burrows. Inspector Comments: Active burrow hole has been grouted since initial fall inspection.	38.595862 ° -121.466403 °	38.595862 ° -121.466403 °	1

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2009 Levee Inspection Results

American River Flood Control District

Waterway			Bank	Unit Miles
Unit No. 04 American River			Left	10.97
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/17/2009		10/2/2009	
DWR Inspector	Clay Thomas		John Paasch	
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River				Left	10.97	11/06/2009 11/17/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.02	0.02	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.596908 ° -121.506716 °	38.596908 ° -121.506716 °	178 Y
2	0.07	0.07	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.597382 ° -121.506429 °	38.597382 ° -121.506429 °	179 Y
3	0.31	0.47	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Vines and privacy fence within 10-ft of the landside toe or on the levee slope obstruct visibility and access.	38.599835 ° -121.503448 °	38.600762 ° -121.500833 °	1 Y
4	0.72	0.72	Earthen Levee	Encroachments	LS	M	Tree or limb	38.601593 ° -121.496639 °	38.601593 ° -121.496639 °	180 Y
5	0.82	0.82	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.601489 ° -121.495893 °	38.601489 ° -121.495893 °	181 Y
6	1.42	1.42	Earthen Levee	Animal Control	WS	M	Inspector Comments: Rodent burrows on levee slope have led to erosion of the hinge point.	38.600379 ° -121.484082 °	38.600379 ° -121.484082 °	182 Y
7	2.40	2.45	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: This portion of the levee was home to a "tent city" making spraying and mowing politically difficult for the LMA. Maintenance to resume next spring.	38.590647 ° -121.471880 °	38.590094 ° -121.471241 °	183 Y
8	2.45	2.45	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	38.590094 ° -121.471241 °	38.590094 ° -121.471241 °	184 Y
9	2.68	2.68	Earthen Levee	Encroachments	LS	CO	Buildings Inspector Comments: Bell Marine	38.588913 ° -121.467210 °	38.588913 ° -121.467210 °	2 Y
10	2.73	2.86	Earthen Levee	Encroachments	LS	M	Abandoned vehicles Inspector Comments: Bell Marine	38.587939 ° -121.466635 °	38.587299 ° -121.464320 °	3 Y
11	2.84	2.84	Earthen Levee	Encroachments	WS	M	Debris Inspector Comments: Bell Marine	38.587272 ° -121.464768 °	38.587272 ° -121.464768 °	4 Y
12	2.87	2.87	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.587297 ° -121.464219 °	38.587297 ° -121.464219 °	185 Y
13	2.92	2.96	Earthen Levee	Encroachments	LS	CO	Buildings Inspector Comments: City of Sacramento building.	38.587251 ° -121.463237 °	38.587318 ° -121.462513 °	5 Y
14	3.88	3.88	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Bamboo privacy fence within 10-ft of the landside toe obstructs visibility.	38.586327 ° -121.447373 °	38.586327 ° -121.447373 °	8 Y
15	3.90	3.90	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Overgrown landscaping within 10-ft of the levee toe obstructs access and visibility.	38.586154 ° -121.447116 °	38.586154 ° -121.447116 °	7 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway					Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River					Left	10.97	11/06/2009 11/17/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
16	3.90	3.90	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: phot Privacy fence within 10-ft of the landside toe obstructs visibility.	38.586154 ° -121.447115 °	38.586154 ° -121.447115 °	6
17	3.91	3.91	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence on the levee slope obstructs access and visibility.	38.586047 ° -121.446975 °	38.586047 ° -121.446975 °	9 Y
18	3.92	3.92	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.585951 ° -121.446845 °	38.585951 ° -121.446845 °	220
19	3.94	3.94	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Landscaping and privacy fence obstruct access and visibility within 10-ft of the levee toe.	38.585761 ° -121.446622 °	38.585761 ° -121.446622 °	10 Y
20	3.95	3.95	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Privacy fence and landscaping within 10-ft of the levee toe obstruct access and visibility.	38.585639 ° -121.446451 °	38.585639 ° -121.446451 °	11
21	3.97	3.97	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Privacy fence and landscaping within 10-ft of the levee toe obstruct access and visibility.	38.585455 ° -121.446225 °	38.585455 ° -121.446225 °	12
22	3.98	3.98	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Pink cement block fence obstructs access and visibility.	38.585325 ° -121.446059 °	38.585325 ° -121.446059 °	13
23	4.00	4.00	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Privacy fence and helix pencil shrubs planted within 10-ft of the levee toe obstruct access and visibility.	38.585175 ° -121.445883 °	38.585175 ° -121.445883 °	14
24	4.01	4.01	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Privacy fence and evergreen shrub landscaping within 10-ft of the levee toe obstruct access and visibility.	38.585021 ° -121.445678 °	38.585021 ° -121.445678 °	15
25	4.02	4.02	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Privacy fence and landscaping within 10-ft of the levee toe obstruct access and visibility.	38.584885 ° -121.445520 °	38.584885 ° -121.445520 °	16 Y
26	4.03	4.03	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Privacy fence and maple tree landscaping within 10-ft of the levee toe obstruct access and visibility.	38.584810 ° -121.445403 °	38.584810 ° -121.445403 °	17
27	4.04	4.04	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden fence between orange trees is within 10-ft of the levee toe.	38.584694 ° -121.445255 °	38.584694 ° -121.445255 °	18

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway					Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River					Left	10.97	11/06/2009 11/17/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	
28	4.07	4.07	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Privacy fence within 10-ft of the levee toe obstruct access and visibility.	38.584459 ° -121.444951 °	38.584459 ° -121.444951 °	19
29	4.08	4.08	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Landscaping on cyclone fence within 10-ft of levee toe obstructs access and visibility.	38.584354 ° -121.444792 °	38.584354 ° -121.444792 °	186 Y
30	4.09	4.09	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Privacy fence and shed within 10-ft of the levee toe obstruct access and visibility.	38.584243 ° -121.444647 °	38.584243 ° -121.444647 °	20
31	4.10	4.10	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Palms and other landscaping on levee slope, as well as the wooden privacy fence within 10-ft of the levee toe obstruct access and visibility.	38.584129 ° -121.444485 °	38.584129 ° -121.444485 °	21
32	4.11	4.11	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Cement block and wooden fence as well as the landscape planting are within 10-ft of the levee slope and obstruct access and visibility.	38.584034 ° -121.444322 °	38.584034 ° -121.444322 °	22
33	4.12	4.12	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Cement block and wooden fence obstruct visibility.	38.583935 ° -121.444150 °	38.583935 ° -121.444150 °	23
34	4.14	4.14	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Orange, olive and other trees and landscaping obstruct access and visibility.	38.583841 ° -121.443977 °	38.583841 ° -121.443977 °	187
35	4.15	4.15	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Cement block fence with iron top built into levee slope. Landscaping within 10-ft of the levee toe obstruct access and visibility.	38.583749 ° -121.443820 °	38.583749 ° -121.443820 °	188 Y
36	4.16	4.16	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Retaining wall is built into the levee slope. Steps, rail and landscaping on the levee slope.	38.583652 ° -121.443640 °	38.583652 ° -121.443640 °	189
37	4.17	4.17	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Planter boxes built into levee slope. Wooden fence obstructs visibility. Pool is just outside 10-ft from levee toe.	38.583559 ° -121.443485 °	38.583559 ° -121.443485 °	190
38	4.19	4.19	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wooden privacy fence within 10-ft of the levee toe obstruct access and visibility.	38.583355 ° -121.443123 °	38.583355 ° -121.443123 °	191
39	4.21	4.21	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wooden privacy fence obstructs visibility. Retaining wall built into levee toe.	38.583265 ° -121.442965 °	38.583265 ° -121.442965 °	24 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River				Left	10.97	11/06/2009 11/17/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
40	4.23	4.23	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Ivy and vine growth on cyclone fence obstruct visibility. Steps and landscaping built up levee slope.	38.583031 ° -121.442620 °	38.583031 ° -121.442620 °	192
41	4.25	4.25	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Landscaping on chain link fence partially obstructs visibility.	38.582824 ° -121.442298 °	38.582824 ° -121.442298 °	193
42	4.27	4.27	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Planting boxes built into levee slope.	38.582716 ° -121.442128 °	38.582716 ° -121.442128 °	194
43	4.28	4.28	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Garden planted on levee slope.	38.582802 ° -121.442387 °	38.582802 ° -121.442387 °	25
44	4.29	4.29	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wooden fence within 10-ft of the levee toe. Garden and ramp built on levee slope.	38.582479 ° -121.441768 °	38.582479 ° -121.441768 °	26
45	4.31	4.31	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Landscaping planted on levee slope.	38.582333 ° -121.441506 °	38.582333 ° -121.441506 °	195
46	4.33	4.33	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wooden privacy fence obstructs visibility.	38.582223 ° -121.441264 °	38.582223 ° -121.441264 °	27
47	4.33	4.33	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Cement block fence obstructs access and visibility.	38.582186 ° -121.441160 °	38.582186 ° -121.441160 °	28
48	4.35	4.35	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Large flowering bush on levee slope. Wooden fence located at the levee toe obstructs access and visibility.	38.582083 ° -121.440875 °	38.582083 ° -121.440875 °	29
49	4.37	4.37	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Picket fence on retaining wall within 10-ft of levee slope obstructs visibility.	38.581937 ° -121.440479 °	38.581937 ° -121.440479 °	196 Y
50	4.38	4.38	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Privet planted within 10-ft of the levee toe.	38.581863 ° -121.440292 °	38.581863 ° -121.440292 °	197
51	4.40	4.40	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Privacy fence and landscaping within 10-ft of the levee toe obstruct access and visibility.	38.581788 ° -121.440086 °	38.581788 ° -121.440086 °	198
52	4.41	4.41	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Privacy fence and landscaping within 10-ft of the levee toe obstruct access and visibility.	38.581724 ° -121.439891 °	38.581724 ° -121.439891 °	30 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway					Bank	Unit Miles	Inspection Start/End		Inspector
Unit No. 04 American River					Left	10.97	11/06/2009 11/17/2009		John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
53	4.45	4.45	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Privacy fence and within 10-ft of the levee toe obstruct access and visibility.	38.581495 ° -121.439129 °	38.581495 ° -121.439129 °	31
54	4.48	4.48	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: No fence. Landscaping obstructs access and visibility.	38.581401 ° -121.438708 °	38.581401 ° -121.438708 °	32
55	4.49	4.49	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Large photinia obstructs visibility.	38.581359 ° -121.438524 °	38.581359 ° -121.438524 °	33
56	4.51	4.51	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Landscaping on levee slope obstructs visibility.	38.581282 ° -121.438169 °	38.581282 ° -121.438169 °	34
57	4.51	4.51	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wooden fence within 10-ft of the levee toe obstructs access and visibility.	38.581237 ° -121.437978 °	38.581237 ° -121.437978 °	35
58	4.53	4.53	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wooden fence is within 10-ft of the levee toe.	38.581205 ° -121.437830 °	38.581205 ° -121.437830 °	199
59	4.54	4.54	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Privacy fence, persimmon tree and landscaping within 10-ft of the levee toe obstruct access and visibility.	38.581178 ° -121.437584 °	38.581178 ° -121.437584 °	200
60	4.55	4.55	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Privacy fence within 10-ft of the levee toe obstruct access and visibility.	38.581155 ° -121.437320 °	38.581155 ° -121.437320 °	201
61	4.57	4.57	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Privacy fence near pump station limits access and visibility.	38.581153 ° -121.437079 °	38.581153 ° -121.437079 °	36 Y
62	4.65	4.65	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Trees and vines on the levee toe obstruct visibility.	38.580944 ° -121.435651 °	38.580944 ° -121.435651 °	37 Y
63	4.67	4.67	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Landscape planting within 10-ft of the landside toe against 3-ft wooden slat fence.	38.580910 ° -121.435324 °	38.580910 ° -121.435324 °	38
64	4.69	4.69	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Privacy fence and landscaping within 10-ft of the levee toe obstruct access and visibility.	38.580840 ° -121.434901 °	38.580840 ° -121.434901 °	39
65	4.71	4.71	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.580951 ° -121.434546 °	38.580951 ° -121.434546 °	221

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River				Left	10.97	11/06/2009 11/17/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
66	4.72	4.72	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.580766 ° -121.434420 °	38.580766 ° -121.434420 °	202
67	4.73	4.73	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Privacy fence within 10-ft of the levee toe obstruct access and visibility.	38.580759 ° -121.434294 °	38.580759 ° -121.434294 °	40 Y
68	4.74	4.74	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Privacy fence and landscaping within 10-ft of the levee toe obstruct access and visibility.	38.580753 ° -121.434077 °	38.580753 ° -121.434077 °	41
69	4.75	4.75	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Privacy fence within 10-ft of the levee toe obstruct access and visibility.	38.580741 ° -121.433899 °	38.580741 ° -121.433899 °	42
70	4.77	4.77	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Privacy fence and storage sheds within 10-ft of the levee toe obstruct access and visibility.	38.580731 ° -121.433490 °	38.580731 ° -121.433490 °	43
71	4.79	4.79	Earthen Levee	Encroachments	LS	M	Material Inspector Comments: Cinderblocks on levee toe limit access.	38.580724 ° -121.433122 °	38.580724 ° -121.433122 °	203
72	4.81	4.81	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Ivy along toe obstructs visibility.	38.580723 ° -121.432823 °	38.580723 ° -121.432823 °	204
73	4.82	4.82	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Privacy fence and landscape prunings on levee slope and toe.	38.580723 ° -121.432577 °	38.580723 ° -121.432577 °	205
74	4.85	4.85	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Lemon tree and vines obstruct visibility.	38.580747 ° -121.432039 °	38.580747 ° -121.432039 °	44
75	4.87	4.87	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Fig tree obstructs visibility and access.	38.580778 ° -121.431704 °	38.580778 ° -121.431704 °	206
76	4.90	4.90	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Garden activities obstruct visibility within 10-ft of the levee toe.	38.580809 ° -121.431274 °	38.580809 ° -121.431274 °	207
77	4.93	4.93	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wooden fence with bracing obstructs access and visibility.	38.580846 ° -121.430699 °	38.580846 ° -121.430699 °	45
78	5.08	5.08	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Privacy fence and landscaping within 10-ft of the levee toe obstruct access and visibility.	38.581001 ° -121.427854 °	38.581001 ° -121.427854 °	46 Y
79	5.09	5.09	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.581176 ° -121.427793 °	38.581176 ° -121.427793 °	219

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River				Left	10.97	11/06/2009 11/17/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	
80	5.11	5.11	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.581112 ° -121.427457 °	38.581112 ° -121.427457 °	218 Y
81	5.13	5.13	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Privacy fence and landscaping within 10-ft of the levee toe obstruct access and visibility.	38.580913 ° -121.427119 °	38.580913 ° -121.427119 °	208
82	5.15	5.15	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Chain link fence, helix sky pencil, and landscaping within 10-ft of the levee toe obstruct access and visibility.	38.580773 ° -121.426691 °	38.580773 ° -121.426691 °	47
83	5.17	5.17	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wood privacy fence and landscaping within 10-ft of the levee toe obstruct access and visibility.	38.580622 ° -121.426372 °	38.580622 ° -121.426372 °	48 Y
84	5.36	5.36	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.579010 ° -121.423762 °	38.579010 ° -121.423762 °	217 Y
85	5.45	5.45	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wood privacy fence within 10-ft of the levee toe obstruct access and visibility.	38.577589 ° -121.423350 °	38.577589 ° -121.423350 °	49
86	5.50	5.50	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Oleanders within 10-ft of the levee toe obstruct access and visibility.	38.576883 ° -121.423216 °	38.576883 ° -121.423216 °	209
87	5.56	5.56	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Levee slope is heavily landscaped.	38.576153 ° -121.423134 °	38.576153 ° -121.423134 °	50
88	5.57	5.57	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Landscaping at levee toe obstructs visibility.	38.575903 ° -121.423122 °	38.575903 ° -121.423122 °	51
89	5.61	5.61	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Helix sky pencil trees within 10-ft of the levee toe obstruct visibility and access.	38.575379 ° -121.423201 °	38.575379 ° -121.423201 °	52
90	5.63	5.63	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Wood privacy fence, helix sky pencil, vines and landscaping within 10-ft of the levee toe obstruct access and visibility.	38.575250 ° -121.423240 °	38.575250 ° -121.423240 °	53 Y
91	5.64	5.64	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wood privacy fence and landscaping within 10-ft of the levee toe obstruct access and visibility.	38.575093 ° -121.423263 °	38.575093 ° -121.423263 °	54
92	5.65	5.65	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows. Inspector Comments: Rodent activity is evident.	38.574780 ° -121.423052 °	38.574780 ° -121.423052 °	216

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River				Left	10.97	11/06/2009 11/17/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
93	5.66	5.66	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wood privacy fence within 10-ft of the levee toe obstructs visibility.	38.574837 ° -121.423297 °	38.574837 ° -121.423297 °	55
94	5.67	5.67	Earthen Levee	Encroachments	LS	CO	Buildings Inspector Comments: Cement block building on levee slope obstructs access.	38.574648 ° -121.423348 °	38.574648 ° -121.423348 °	56
95	5.72	5.72	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wood privacy fence with ivy obstructs visibility.	38.573927 ° -121.423480 °	38.573927 ° -121.423480 °	57
96	5.75	5.75	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Garden built on levee slope.	38.573547 ° -121.423583 °	38.573547 ° -121.423583 °	58
97	5.76	5.76	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Brick fence and landscaping within 10-ft of the levee toe obstructs access and visibility.	38.573403 ° -121.423642 °	38.573403 ° -121.423642 °	59
98	5.77	5.77	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Fig, maple and other landscaping obstructs visibility.	38.573240 ° -121.423697 °	38.573240 ° -121.423697 °	60
99	5.79	5.79	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Dense ivy and shrubs are within 10-ft of the levee toe.	38.572918 ° -121.423760 °	38.572918 ° -121.423760 °	61
100	5.81	5.81	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Citrus tree and slope landscaping obstructs visibility.	38.572748 ° -121.423818 °	38.572748 ° -121.423818 °	62
101	5.83	5.83	Earthen Levee	Encroachments	LS	CO	Buildings Inspector Comments: Tin building within 10-ft of the levee toe.	38.572325 ° -121.423913 °	38.572325 ° -121.423913 °	63
102	5.84	5.84	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Dense shrubs on levee toe.	38.572207 ° -121.423933 °	38.572207 ° -121.423933 °	64
103	5.85	5.85	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Extended privacy fence within 10-ft of levee toe.	38.572067 ° -121.423970 °	38.572067 ° -121.423970 °	65
104	5.87	5.87	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Privacy fence is within 10-ft of levee toe.	38.571733 ° -121.424055 °	38.571733 ° -121.424055 °	210
105	5.88	5.88	Earthen Levee	Encroachments	LS	C	Material	38.571685 ° -121.424115 °	38.571685 ° -121.424115 °	67
106	5.88	5.88	Earthen Levee	Encroachments	LS	CO	Buildings	38.571586 ° -121.424097 °	38.571586 ° -121.424097 °	66

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 04 American River				Left	10.97	11/06/2009 11/17/2009	John Paasch	

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
107	5.89	5.89	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Levee slope has been landscaped. This obstructs visibility.	38.571525 ° -121.424152 °	38.571525 ° -121.424152 °	68 Y
108	5.91	5.91	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Levee slope has been landscaped. This obstructs visibility.	38.571243 ° -121.424167 °	38.571243 ° -121.424167 °	69
109	5.92	5.92	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Levee slope has been landscaped. This obstructs visibility.	38.571145 ° -121.424192 °	38.571145 ° -121.424192 °	70
110	5.97	5.97	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.570402 ° -121.424067 °	38.570402 ° -121.424067 °	215 Y
111	5.97	5.97	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Landscaping and garden within 10-ft of the levee toe.	38.570450 ° -121.424237 °	38.570450 ° -121.424237 °	71
112	5.97	5.97	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wood fence and landscaping within 10-ft of the levee toe obstructs visibility.	38.570391 ° -121.424227 °	38.570391 ° -121.424227 °	72
113	6.00	6.00	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Apartment complex privacy fence and shrubs within 10-ft of the slope obstruct visibility.	38.569893 ° -121.424310 °	38.569893 ° -121.424310 °	211
114	6.15	6.15	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Vegetation left at waterside hinge point is within top 20-ft of levee slope.	38.567784 ° -121.423943 °	38.567784 ° -121.423943 °	212 Y
115	6.61	6.61	Earthen Levee	Encroachments	LS	CO	Buildings Inspector Comments: Generator and sheds within 10-ft of levee slope.	38.561643 ° -121.421262 °	38.561643 ° -121.421262 °	73
116	7.29	7.29	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.558201 ° -121.410823 °	38.558201 ° -121.410823 °	213 Y
117	7.70	7.73	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence for seven apartment units is within 10-ft of levee toe and obstructs access and visibility.	38.559177 ° -121.403541 °	38.559218 ° -121.402967 °	74 Y
118	7.75	7.77	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence for seven apartment units is within 10-ft of levee toe and obstructs access and visibility.	38.559230 ° -121.402708 °	38.559261 ° -121.402219 °	75

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River				Left	10.97	11/06/2009 11/17/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
119	7.80	7.82	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence for seven apartment units is within 10-ft of levee toe and obstructs access and visibility.	38.559308 ° -121.401717 °	38.559309 ° -121.401388 °	76
120	7.83	7.86	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence for seven apartment units is within 10-ft of levee toe and obstructs access and visibility.	38.559330 ° -121.401162 °	38.559366 ° -121.400683 °	77
121	7.88	7.90	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence for seven apartment units is within 10-ft of levee toe and obstructs access and visibility.	38.559379 ° -121.400354 °	38.559435 ° -121.399944 °	78
122	7.91	7.94	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence for seven apartment units is within 10-ft of levee toe and obstructs access and visibility.	38.559514 ° -121.399700 °	38.559643 ° -121.399248 °	79 Y
123	7.92	7.92	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	38.559604 ° -121.399711 °	38.559604 ° -121.399711 °	234
124	7.92	7.92	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Landscaping trees and bushes obstruct access and visibility.	38.559560 ° -121.399534 °	38.559560 ° -121.399534 °	222
125	7.95	7.95	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.559783 ° -121.399178 °	38.559783 ° -121.399178 °	233
126	7.96	7.98	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence for seven apartment units is within 10-ft of levee toe and obstructs access and visibility.	38.559753 ° -121.398982 °	38.559911 ° -121.398506 °	80
127	7.99	7.99	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Landscaping trees and bushes within 10-ft of levee toe obstruct visibility.	38.559957 ° -121.398401 °	38.559957 ° -121.398401 °	223
128	8.00	8.03	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence for seven apartment units is within 10-ft of levee toe and obstructs access and visibility.	38.559994 ° -121.398318 °	38.560185 ° -121.397845 °	224
129	8.04	8.07	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence for seven apartment units is within 10-ft of levee toe and obstructs access and visibility.	38.560281 ° -121.397604 °	38.560435 ° -121.397239 °	81
130	8.09	8.09	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Brick fence is within 10-ft of levee toe, obstructing access and visibility.	38.560537 ° -121.396912 °	38.560537 ° -121.396912 °	82 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River				Left	10.97	11/06/2009 11/17/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	
131	8.10	8.10	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Brick fence is within 10-ft of levee toe and obstructs access and visibility.	38.560647 ° -121.396660 °	38.560647 ° -121.396660 °	83
132	8.11	8.11	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Brick fence is within 10-ft of levee toe and obstructs access and visibility.	38.560728 ° -121.396471 °	38.560728 ° -121.396471 °	84
133	8.13	8.13	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Brick fence is within 10-ft of levee toe and obstructs access and visibility.	38.560845 ° -121.396189 °	38.560845 ° -121.396189 °	85
134	8.14	8.14	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Brick fence is within 10-ft of levee toe and obstructs access and visibility.	38.560907 ° -121.396043 °	38.560907 ° -121.396043 °	86 Y
135	8.15	8.15	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Brick fence is within 10-ft of levee toe and obstructs access and visibility.	38.561008 ° -121.395817 °	38.561008 ° -121.395817 °	87
136	8.18	8.18	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Landscaping along chain link fence within 10-ft of levee toe obstructs access and visibility.	38.561187 ° -121.395351 °	38.561187 ° -121.395351 °	225
137	8.20	8.20	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence within 10-ft of levee toe obstructs access and visibility.	38.561343 ° -121.394998 °	38.561343 ° -121.394998 °	88 Y
138	8.22	8.22	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Fence and landscaping arbor within 10-ft of levee toe obstructs access and visibility.	38.561467 ° -121.394728 °	38.561467 ° -121.394728 °	89
139	8.23	8.23	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Cement block fence within 10-ft of the levee toe.	38.561544 ° -121.394494 °	38.561544 ° -121.394494 °	90
140	8.25	8.25	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Cement block fence and landscaping within 10-ft of levee toe obstructs access and visibility.	38.561593 ° -121.394315 °	38.561593 ° -121.394315 °	91
141	8.25	8.25	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Cement block fence and landscaping within 10-ft of levee toe obstructs access and visibility.	38.561658 ° -121.394157 °	38.561658 ° -121.394157 °	92
142	8.27	8.27	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden fence, strung tarps, and landscaping within 10-ft of levee toe obstructs access and visibility.	38.561750 ° -121.393917 °	38.561750 ° -121.393917 °	93 Y
143	8.28	8.28	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wood privacy fence and pool within 10-ft of levee toe obstructs access and visibility.	38.561799 ° -121.393758 °	38.561799 ° -121.393758 °	94

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River				Left	10.97	11/06/2009 11/17/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
144	8.29	8.29	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wood privacy fence within 10-ft of levee toe obstructs access and visibility.	38.561900 ° -121.393547 °	38.561900 ° -121.393547 °	95 Y
145	8.31	8.31	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wood privacy fence within 10-ft of levee toe obstructs access and visibility.	38.561980 ° -121.393359 °	38.561980 ° -121.393359 °	96
146	8.31	8.31	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wood privacy fence within 10-ft of levee toe obstructs access and visibility.	38.561986 ° -121.393343 °	38.561986 ° -121.393343 °	97
147	8.32	8.32	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wood privacy fence within 10-ft of levee toe obstructs access and visibility.	38.562054 ° -121.393190 °	38.562054 ° -121.393190 °	98
148	8.32	8.32	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.562237 ° -121.393153 °	38.562237 ° -121.393153 °	232
149	8.33	8.33	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wood privacy fence within 10-ft of levee toe obstructs access and visibility.	38.562120 ° -121.392983 °	38.562120 ° -121.392983 °	99
150	8.34	8.34	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wood privacy fence within 10-ft of levee toe obstructs access and visibility.	38.562182 ° -121.392778 °	38.562182 ° -121.392778 °	100
151	8.39	8.39	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wood privacy fence within 10-ft of levee toe obstructs access and visibility.	38.562508 ° -121.392037 °	38.562508 ° -121.392037 °	101
152	8.40	8.40	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.562769 ° -121.391831 °	38.562769 ° -121.391831 °	231
153	8.44	8.44	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Helix sky pencil along chain link fence is within 10-ft of the levee toe.	38.562858 ° -121.391149 °	38.562858 ° -121.391149 °	102
154	8.47	8.47	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wood privacy fence within 10-ft of levee toe obstructs access and visibility.	38.563042 ° -121.390692 °	38.563042 ° -121.390692 °	103
155	8.47	8.47	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.563163 ° -121.390764 °	38.563163 ° -121.390764 °	230
156	8.48	8.48	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wood privacy fence within 10-ft of levee toe obstructs access and visibility.	38.563108 ° -121.390452 °	38.563108 ° -121.390452 °	104
157	8.50	8.50	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.563342 ° -121.390252 °	38.563342 ° -121.390252 °	229

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway					Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River					Left	10.97	11/06/2009 11/17/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
158	8.51	8.51	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Palms planted within 10-ft of the levee toe.	38.563238 ° -121.390073 °	38.563238 ° -121.390073 °	105
159	8.52	8.52	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wood privacy fence within 10-ft of levee toe obstructs access and visibility. Block wall built into the levee.	38.563308 ° -121.389885 °	38.563308 ° -121.389885 °	106
160	8.54	8.54	Earthen Levee	Encroachments	LS	CO	Landscaping	38.563511 ° -121.389509 °	38.563511 ° -121.389509 °	107
161	8.55	8.55	Earthen Levee	Encroachments	LS	CO	Landscaping	38.563587 ° -121.389313 °	38.563587 ° -121.389313 °	108
162	8.56	8.56	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Redwood and ivy within 10-ft of levee toe.	38.566948 ° -121.371562 °	38.566948 ° -121.371562 °	236
163	8.57	8.57	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wood privacy fence within 10-ft of levee toe obstructs access and visibility.	38.563580 ° -121.389140 °	38.563580 ° -121.389140 °	109
164	8.58	8.58	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wood privacy fence within 10-ft of levee toe obstructs access and visibility.	38.563732 ° -121.388930 °	38.563732 ° -121.388930 °	110
165	8.59	8.59	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Garden, trees and cactus planted against the levee toe.	38.563793 ° -121.388758 °	38.563793 ° -121.388758 °	226
166	8.60	8.60	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wood privacy fence within 10-ft of levee toe obstructs access and visibility.	38.563820 ° -121.388518 °	38.563820 ° -121.388518 °	111
167	8.61	8.61	Earthen Levee	Encroachments	LS	CO	Landscaping	38.563877 ° -121.388345 °	38.563877 ° -121.388345 °	112 Y
168	8.61	8.61	Earthen Levee	Encroachments	LS	CO	Landscaping	38.563877 ° -121.388343 °	38.563877 ° -121.388343 °	113
169	8.63	8.63	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Ivy and orange tree obstruct visibility.	38.563945 ° -121.388137 °	38.563945 ° -121.388137 °	114
170	8.63	8.63	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.564120 ° -121.388240 °	38.564120 ° -121.388240 °	228
171	8.65	8.65	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wood privacy fence and 2-story play house within 10-ft of levee toe obstructs access and visibility.	38.564047 ° -121.387743 °	38.564047 ° -121.387743 °	115

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River				Left	10.97	11/06/2009 11/17/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
172	8.66	8.66	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wood privacy fence and wood out building within 10-ft of levee toe obstructs access and visibility.	38.564033 ° -121.387572 °	38.564033 ° -121.387572 °	117
173	8.67	8.67	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wood privacy fence within 10-ft of levee toe obstructs access and visibility.	38.564133 ° -121.387318 °	38.564133 ° -121.387318 °	116
174	8.68	8.68	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wood privacy fence within 10-ft of levee toe obstructs access and visibility.	38.564133 ° -121.387092 °	38.564133 ° -121.387092 °	118
175	8.70	8.70	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wood privacy fence within 10-ft of levee toe obstructs access and visibility.	38.564217 ° -121.386846 °	38.564217 ° -121.386846 °	119
176	8.71	8.71	Earthen Levee	Encroachments	LS	PO	Landscaping	38.564268 ° -121.386599 °	38.564268 ° -121.386599 °	227
177	8.98	8.98	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Chain link fence with privacy slats and barbed wire within 10-ft of levee toe obstructs access and visibility.	38.565352 ° -121.382044 °	38.565352 ° -121.382044 °	235
178	9.54	9.54	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Bushes within 10-ft of levee toe obstructs visibility.	38.566849 ° -121.372166 °	38.566849 ° -121.372166 °	120
179	9.57	9.57	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Redwoods and ivy along fence within 10-ft of levee toe.	38.566938 ° -121.371550 °	38.566938 ° -121.371550 °	237
180	9.61	9.61	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Oleander bushes and shrubs within 10-ft of landside toe.	38.567058 ° -121.370954 °	38.567058 ° -121.370954 °	121
181	9.64	9.64	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Trees and ground cover within 10-ft of levee toe.	38.567181 ° -121.370366 °	38.567181 ° -121.370366 °	122
182	9.66	9.66	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Trees, bushes and ground cover within 10-ft of levee toe.	38.567285 ° -121.369964 °	38.567285 ° -121.369964 °	123
183	9.67	9.67	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Ivy and vines on chain link fence within 10-ft of levee toe.	38.567242 ° -121.369858 °	38.567242 ° -121.369858 °	124
184	9.69	9.69	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Dense golden ivy on C/L fence obstructs access and visibility.	38.567360 ° -121.369555 °	38.567360 ° -121.369555 °	125

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River				Left	10.97	11/06/2009 11/17/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
185	9.70	9.70	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Vines and ground cover within 10-ft of levee toe.	38.567387 ° -121.369358 °	38.567387 ° -121.369358 °	126
186	9.72	9.72	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Ground cover on levee slope.	38.567451 ° -121.368962 °	38.567451 ° -121.368962 °	127
187	9.74	9.74	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence within 10-ft of levee toe.	38.567493 ° -121.368633 °	38.567493 ° -121.368633 °	128
188	9.75	9.75	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Trees and vines along C/L fence within 10-ft of levee toe.	38.567540 ° -121.368467 °	38.567540 ° -121.368467 °	129
189	9.78	9.78	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Tall hedge obstructs access and visibility.	38.567626 ° -121.367921 °	38.567626 ° -121.367921 °	130
190	9.79	9.79	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Tall hedge obstructs access and visibility.	38.567680 ° -121.367674 °	38.567680 ° -121.367674 °	131
191	9.82	9.82	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Trees and ivy on levee slope obstruct access and visibility.	38.567772 ° -121.367227 °	38.567772 ° -121.367227 °	132
192	9.84	9.84	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Lemon tree, palm, sky pencil and ivy planted within 10-ft of levee toe obstructs access and visibility.	38.567856 ° -121.366892 °	38.567856 ° -121.366892 °	133
193	9.86	9.86	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Ivy, hedge and play house is within 10-ft of levee toe.	38.567873 ° -121.366410 °	38.567873 ° -121.366410 °	134
194	10.02	10.02	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Tall hedge and ivy within 10-ft of landside levee toe.	38.568542 ° -121.363643 °	38.568542 ° -121.363643 °	135
195	10.03	10.03	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Tall hedge and ivy within 10-ft of landside levee toe.	38.568620 ° -121.363453 °	38.568620 ° -121.363453 °	136
196	10.07	10.07	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Ivy on levee slope and Juniper at levee toe.	38.568833 ° -121.362783 °	38.568833 ° -121.362783 °	137
197	10.09	10.09	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Landscaping on levee slope.	38.568918 ° -121.362533 °	38.568918 ° -121.362533 °	238

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River						Left	10.97	11/06/2009 11/17/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
198	10.10	10.10	Earthen Levee	Encroachments	LS	CO	Fences	38.568953 ° -121.362396 °	38.568953 ° -121.362396 °	138
199	10.11	10.11	Earthen Levee	Encroachments	LS	PO	Landscaping	38.569077 ° -121.362168 °	38.569077 ° -121.362168 °	139
200	10.16	10.16	Earthen Levee	Encroachments	LS	PO	Landscaping	38.569233 ° -121.361337 °	38.569233 ° -121.361337 °	140
201	10.18	10.18	Earthen Levee	Encroachments	LS	CO	Buildings	38.569293 ° -121.361002 °	38.569293 ° -121.361002 °	176
202	10.34	10.37	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden fence behind six apartment units is within 10-ft of levee slope.	38.569982 ° -121.358134 °	38.570118 ° -121.357604 °	141
203	10.38	10.40	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden fence behind six apartment units is within 10-ft of levee slope.	38.570175 ° -121.357390 °	38.570229 ° -121.357041 °	142 Y
204	10.42	10.44	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden fence behind six apartment units is within 10-ft of levee slope.	38.570257 ° -121.356783 °	38.570297 ° -121.356403 °	143
205	10.45	10.48	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden fence behind six apartment units is within 10-ft of levee slope.	38.570325 ° -121.356185 °	38.570397 ° -121.355757 °	144
206	10.48	10.51	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden fence behind six apartment units is within 10-ft of levee slope.	38.570417 ° -121.355625 °	38.570500 ° -121.355151 °	145
207	10.52	10.52	Earthen Levee	Encroachments	LS	PO	Fences	38.570513 ° -121.355056 °	38.570513 ° -121.355056 °	146
208	10.53	10.53	Earthen Levee	Encroachments	LS	PO	Fences	38.570542 ° -121.354772 °	38.570542 ° -121.354772 °	147
209	10.56	10.56	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wooden privacy fence obstructs visibility and access.	38.570524 ° -121.354359 °	38.570524 ° -121.354359 °	148
210	10.58	10.58	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wooden privacy fence is within 10-ft of levee toe.	38.570234 ° -121.353862 °	38.570234 ° -121.353862 °	149
211	10.60	10.60	Earthen Levee	Encroachments	CR	C	Equipment Inspector Comments: Mayhew repair has crown blocked.	38.570230 ° -121.353798 °	38.570230 ° -121.353798 °	177
212	10.60	10.60	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wooden privacy fence within 10-ft of levee toe.	38.570095 ° -121.353807 °	38.570095 ° -121.353807 °	150

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River				Left	10.97	11/06/2009 11/17/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
213	10.62	10.62	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence within 10-ft of levee toe.	38.569921 ° -121.353643 °	38.569921 ° -121.353643 °	151 Y
214	10.63	10.63	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wooden privacy fence within 10-ft of levee toe.	38.569758 ° -121.353535 °	38.569758 ° -121.353535 °	152
215	10.66	10.66	Earthen Levee	Encroachments	LS	PO	Landscaping	38.569315 ° -121.353355 °	38.569315 ° -121.353355 °	239
216	10.67	10.67	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence and ivy within 10-ft of levee toe.	38.569166 ° -121.353272 °	38.569166 ° -121.353272 °	153
217	10.68	10.68	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wooden privacy fence within 10-ft of levee toe.	38.569020 ° -121.353313 °	38.569020 ° -121.353313 °	154
218	10.69	10.69	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Trees and bushes are within 10-ft of the levee toe.	38.568892 ° -121.353162 °	38.568892 ° -121.353162 °	155
219	10.71	10.71	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wooden privacy fence and landscaping within 10-ft of levee toe.	38.568713 ° -121.353150 °	38.568713 ° -121.353150 °	156
220	10.71	10.71	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Tall hedge and vine on levee toe.	38.568608 ° -121.353054 °	38.568608 ° -121.353054 °	157
221	10.73	10.73	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wooden privacy fence within 10-ft of levee toe.	38.568355 ° -121.353033 °	38.568355 ° -121.353033 °	158
222	10.73	10.73	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wooden privacy fence within 10-ft of levee toe.	38.568313 ° -121.352941 °	38.568313 ° -121.352941 °	159
223	10.74	10.74	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Tall wooden privacy fence within 10-ft of levee toe.	38.568188 ° -121.352864 °	38.568188 ° -121.352864 °	160
224	10.75	10.75	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence and vine within 10-ft of levee toe.	38.568058 ° -121.352785 °	38.568058 ° -121.352785 °	161
225	10.80	10.80	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wooden privacy fence within 10-ft of levee toe.	38.567402 ° -121.352415 °	38.567402 ° -121.352415 °	162

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River				Left	10.97	11/06/2009 11/17/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
226	10.82	10.82	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence and landscaping within 10-ft of levee toe.	38.567250 ° -121.352341 °	38.567250 ° -121.352341 °	163
227	10.83	10.83	Earthen Levee	Encroachments	LS	CO	Landscaping	38.567100 ° -121.352273 °	38.567100 ° -121.352273 °	164
228	10.84	10.84	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wooden privacy fence within 10-ft of levee toe.	38.566981 ° -121.352213 °	38.566981 ° -121.352213 °	170
229	10.85	10.85	Earthen Levee	Encroachments	LS	PO	Landscaping	38.566823 ° -121.352117 °	38.566823 ° -121.352117 °	240
230	10.86	10.86	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wooden privacy fence within 10-ft of levee toe.	38.566705 ° -121.352063 °	38.566705 ° -121.352063 °	166
231	10.87	10.87	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence and tall hedge within 10-ft of levee toe.	38.566545 ° -121.352004 °	38.566545 ° -121.352004 °	171
232	10.88	10.88	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Wooden privacy fence within 10-ft of levee toe. Tree limb on levee slope.	38.566399 ° -121.351931 °	38.566399 ° -121.351931 °	169
233	10.89	10.89	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Wooden privacy fence ivy and vine planted within 10-ft of levee toe.	38.566233 ° -121.351848 °	38.566233 ° -121.351848 °	167
234	10.91	10.91	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Wooden privacy fence within 10-ft of levee toe.	38.566044 ° -121.351747 °	38.566044 ° -121.351747 °	165
235	10.92	10.94	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence within 10-ft of levee toe.	38.565917 ° -121.351682 °	38.565646 ° -121.351532 °	168

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River	Left	10.97	11/06/2009 11/17/2009	John Paasch

Levee Mile Report Line	1
Start Levee Mile	0.02
End Levee Mile	0.02
Location	Water Side
Category	Earthen Levee
Item	Animal Control
Active rodent burrows present on the waterside slope.	
jpaasch_20091109_190.jpg	



Levee Mile Report Line	3
Start Levee Mile	0.31
End Levee Mile	0.47
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Landscaping on privacy fence within 10-ft of the levee toe limits access and visibility.	
jpaasch_20091109_191.jpg	



Levee Mile Report Line	4
Start Levee Mile	0.72
End Levee Mile	0.72
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Tree limbs present on landside hinge point should be removed.	
jpaasch_20091109_192.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River	Left	10.97	11/06/2009 11/17/2009	John Paasch

Levee Mile Report Line	5
Start Levee Mile	0.82
End Levee Mile	0.82
Location	Land Side
Category	Earthen Levee
Item	Animal Control
Numerous active animal burrows present on levee slope near the lower patrol road.	
jpaasch_20091109_193.jpg	



Levee Mile Report Line	6
Start Levee Mile	1.42
End Levee Mile	1.42
Location	Water Side
Category	Earthen Levee
Item	Animal Control
Numerous active animal burrows present on the waterside slope of the levee.	
jpaasch_20091109_194.jpg	



Levee Mile Report Line	7
Start Levee Mile	2.40
End Levee Mile	2.45
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Photo of minimally acceptable vegetation on landside slope and toe. Annual maintenance was not done due to concerns for the "tent city" which was located here.	
jpaasch_20091109_195.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River	Left	10.97	11/06/2009 11/17/2009	John Paasch

Levee Mile Report Line	10
Start Levee Mile	2.73
End Levee Mile	2.86
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Abandoned vehicles, debris and materials have been placed landside of the levee crown.	
jpaasch_20091109_196.jpg	



Levee Mile Report Line	13
Start Levee Mile	2.92
End Levee Mile	2.96
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Building is placed just off the levee crown.	
jpaasch_20091109_197.jpg	



Levee Mile Report Line	14
Start Levee Mile	3.88
End Levee Mile	3.88
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Fence and landscaping within 10-ft of levee toe obstructs access and visibility.	
jpaasch_20091116_207.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River	Left	10.97	11/06/2009 11/17/2009	John Paasch

Levee Mile Report Line	15
Start Levee Mile	3.90
End Levee Mile	3.90
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Landscaping within 10-ft of the landside toe obstructs access and visibility.	
jpaasch_20091116_209.jpg	



Levee Mile Report Line	17
Start Levee Mile	3.91
End Levee Mile	3.91
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Privacy fence within 10-ft of landside toe obstructs access and visibility.	
jpaasch_20091116_208.jpg	



Levee Mile Report Line	19
Start Levee Mile	3.94
End Levee Mile	3.94
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Fence and landscaping within 10-ft of levee toe obstructs access and visibility.	
jpaasch_20091116_211.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River	Left	10.97	11/06/2009 11/17/2009	John Paasch

Levee Mile Report Line	25
Start Levee Mile	4.02
End Levee Mile	4.02
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Fence and landscaping within 10-ft of levee toe obstructs access and visibility.	
jpaasch_20091116_212.jpg	



Levee Mile Report Line	29
Start Levee Mile	4.08
End Levee Mile	4.08
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Landscaping within 10-ft of levee toe obstructs access and visibility.	
jpaasch_20091116_213.jpg	



Levee Mile Report Line	35
Start Levee Mile	4.15
End Levee Mile	4.15
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Fence and landscaping within 10-ft of levee toe obstructs access and visibility.	
jpaasch_20091116_214.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River	Left	10.97	11/06/2009 11/17/2009	John Paasch

Levee Mile Report Line	39
Start Levee Mile	4.21
End Levee Mile	4.21
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Fence and retaining wall built within 10-ft of levee toe.	
jpaasch_20091116_216.jpg	



Levee Mile Report Line	49
Start Levee Mile	4.37
End Levee Mile	4.37
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Fence within 10-ft of levee toe obstructs access and visibility.	
jpaasch_20091116_215.jpg	



Levee Mile Report Line	52
Start Levee Mile	4.41
End Levee Mile	4.41
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Fence within 10-ft of levee toe obstructs access and visibility.	
jpaasch_20091116_217.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River	Left	10.97	11/06/2009 11/17/2009	John Paasch

Levee Mile Report Line	61
Start Levee Mile	4.57
End Levee Mile	4.57
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Fence and landscaping within 10-ft of levee toe obstructs access and visibility.	
jpaasch_20091116_218.jpg	



Levee Mile Report Line	62
Start Levee Mile	4.65
End Levee Mile	4.65
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Landscaping within 10-ft of levee toe obstructs access and visibility.	
jpaasch_20091116_219.jpg	



Levee Mile Report Line	67
Start Levee Mile	4.73
End Levee Mile	4.73
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Fence within 10-ft of levee toe obstructs access and visibility.	
jpaasch_20091116_220.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River	Left	10.97	11/06/2009 11/17/2009	John Paasch

Levee Mile Report Line	78
Start Levee Mile	5.08
End Levee Mile	5.08
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Fence and landscaping within 10-ft of levee toe obstructs access and visibility.	
jpaasch_20091116_221.jpg	



Levee Mile Report Line	80
Start Levee Mile	5.11
End Levee Mile	5.11
Location	Water Side
Category	Earthen Levee
Item	Animal Control
Animal burrow on the bottom of waterside slope.	
jpaasch_20091116_229.jpg	



Levee Mile Report Line	83
Start Levee Mile	5.17
End Levee Mile	5.17
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Fence and landscaping within 10-ft of levee toe obstructs access and visibility.	
jpaasch_20091116_222.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River	Left	10.97	11/06/2009 11/17/2009	John Paasch

Levee Mile Report Line	84
Start Levee Mile	5.36
End Levee Mile	5.36
Location	Water Side
Category	Earthen Levee
Item	Animal Control

Large animal burrow on waterside slope.

jpaasch_20091116_228.jpg



Levee Mile Report Line	90
Start Levee Mile	5.63
End Levee Mile	5.63
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Fence and landscaping within 10-ft of levee toe obstructs access and visibility.

jpaasch_20091116_223.jpg



Levee Mile Report Line	107
Start Levee Mile	5.89
End Levee Mile	5.89
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Landscaping on and within 10-ft of levee slope obstructs access and visibility.

jpaasch_20091116_224.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River	Left	10.97	11/06/2009 11/17/2009	John Paasch

Levee Mile Report Line	110
Start Levee Mile	5.97
End Levee Mile	5.97
Location	Water Side
Category	Earthen Levee
Item	Animal Control

Large animal burrow on the waterside slope.

jpaasch_20091116_227.jpg



Levee Mile Report Line	114
Start Levee Mile	6.15
End Levee Mile	6.15
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Vegetation near levee crown obstructs visibility and access.

jpaasch_20091116_225.jpg



Levee Mile Report Line	116
Start Levee Mile	7.29
End Levee Mile	7.29
Location	Water Side
Category	Earthen Levee
Item	Animal Control

Rodent activity present on levee slope. Photo of several animal burrows.

jpaasch_20091116_226.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River	Left	10.97	11/06/2009 11/17/2009	John Paasch

Levee Mile Report Line	117
Start Levee Mile	7.70
End Levee Mile	7.73
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Wooden privacy fence within 10-ft of landside levee toe.	
jpaasch_20091119_230.jpg	



Levee Mile Report Line	122
Start Levee Mile	7.91
End Levee Mile	7.94
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Wooden privacy fence and some landscape plantings are within 10-ft of the landside levee toe.	
jpaasch_20091119_231.jpg	



Levee Mile Report Line	130
Start Levee Mile	8.09
End Levee Mile	8.09
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Privacy fence obstructs access and visibility.	
jpaasch_20091119_232.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River	Left	10.97	11/06/2009 11/17/2009	John Paasch

Levee Mile Report Line	134
Start Levee Mile	8.14
End Levee Mile	8.14
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Privacy fence is within 10-ft of landside levee toe.	
jpaasch_20091119_233.jpg	



Levee Mile Report Line	137
Start Levee Mile	8.20
End Levee Mile	8.20
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Privacy fence is within 10-ft of landside levee toe.	
jpaasch_20091119_234.jpg	



Levee Mile Report Line	142
Start Levee Mile	8.27
End Levee Mile	8.27
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Fence, hedge and tarps within 10-ft of the levee toe obstruct access and visibility.	
jpaasch_20091119_239.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River	Left	10.97	11/06/2009 11/17/2009	John Paasch

Levee Mile Report Line	144
Start Levee Mile	8.29
End Levee Mile	8.29
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Privacy fence is within 10-ft of landside levee toe.

jpaasch_20091119_240.jpg



Levee Mile Report Line	167
Start Levee Mile	8.61
End Levee Mile	8.61
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Hedge on the levee toe obstructs visibility.

jpaasch_20091119_238.jpg



Levee Mile Report Line	203
Start Levee Mile	10.38
End Levee Mile	10.40
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Privacy fence within 10-ft of landside levee toe obstructs access and visibility.

jpaasch_20091119_236.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River	Left	10.97	11/06/2009 11/17/2009	John Paasch

Levee Mile Report Line	213
Start Levee Mile	10.62
End Levee Mile	10.62
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Wood privacy fence is within 10-ft of the levee toe.

jpaasch_20091119_237.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2009 Levee Inspection Results

American River Flood Control District

Waterway			Bank	Unit Miles
Unit No. 05 Sacramento River			Left	0.40
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/17/2009		10/2/2009	
DWR Inspector	Clay Thomas		John Paasch	
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector		
Unit No. 05 Sacramento River				Left	0.40	11/06/2009 11/06/2009	John Paasch		

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	0.00	Earthen Levee	Animal Control	WS	A	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows. Inspector Comments: One animal burrow near the crown.	38.596479 ° -121.506937 °	38.596479 ° -121.506937 °	4 Y
2	0.10	0.11	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Landcaping behind Best Western	38.595044 ° -121.506497 °	38.594850 ° -121.506452 °	2
3	0.12	0.14	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Landcaping behind Best Western.	38.594759 ° -121.506427 °	38.594319 ° -121.506392 °	1 Y
4	0.19	0.19	Earthen Levee	Encroachments	LS	M	Tree or limb Inspector Comments: Fallen tree limb on levee slope at old city intake.	38.593669 ° -121.506307 °	38.593669 ° -121.506307 °	3 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Sacramento River	Left	0.40	11/06/2009 11/06/2009	John Paasch

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	Water Side
Category	Earthen Levee
Item	Animal Control
Active animal burrow on the top of waterside levee slope.	
jpaasch_20091109_187.jpg	



Levee Mile Report Line	3
Start Levee Mile	0.12
End Levee Mile	0.14
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Landscaping on landside slope and within 10-ft of the toe limits access and visibility.	
jpaasch_20091109_188.jpg	



Levee Mile Report Line	4
Start Levee Mile	0.19
End Levee Mile	0.19
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Fallen tree limb on the waterside slope needs to be removed.	
jpaasch_20091109_189.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2009 Levee Inspection Results

American River Flood Control District

Waterway			Bank	Unit Miles
Unit No. 06 Linda Creek			Left	1.30
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/17/2009		9/30/2009	
DWR Inspector	Clay Thomas		John Paasch	
Accompanied By			Ilene Wellman-Barbree	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway					Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 06 Linda Creek					Left	1.30	10/02/2009 10/02/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1			Earthen Levee	Vegetation		A	Inspector Comments: Unit 6 is well maintained with no apparent maintenance deficiencies.	°	°	1
								°	°	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2009 Levee Inspection Results

American River Flood Control District

Waterway			Bank	Unit Miles
Unit No. 07 Arcade Creek			Right	1.92
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/17/2009		10/2/2009	
DWR Inspector	Clay Thomas		John Paasch	
Accompanied By			Ilene Wellman-Barbree	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway					Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 07 Arcade Creek					Right	1.92	10/02/2009 11/03/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	
1	0.04	0.53	Earthen Levee	Vegetation	LS	A		38.620666 ° -121.466997 °	38.624640 ° -121.459559 °	35 Y
2	0.34	0.34	Channels	Vegetation & Obstructions	WS	A	Inspector Comments: Large beaver den in Linda Creek.	38.623161 ° -121.462464 °	38.623161 ° -121.462464 °	36 Y
3	0.38	0.38	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.623466 ° -121.461801 °	38.623466 ° -121.461801 °	17
4	0.39	0.39	Earthen Levee	Encroachments	LS	M	Debris Inspector Comments: Tree cuttings on lower patrol road.	38.623486 ° -121.461758 °	38.623486 ° -121.461758 °	18
5	0.72	1.22	Earthen Levee	Vegetation	WS	A	Inspector Comments: Excellent vegetation maintenance.	38.624848 ° -121.456648 °	38.625723 ° -121.447737 °	33 Y
6	0.84	0.84	Earthen Levee	Encroachments	LS	C	Pipe Inspector Comments: 20' length of plastic pipe is left on levee slope.	38.625207 ° -121.454563 °	38.625207 ° -121.454563 °	34
7	0.97	0.97	Channels	Vegetation & Obstructions	WS	A	Inspector Comments: Scattered trash on waterside berm.	38.625809 ° -121.452357 °	38.625809 ° -121.452357 °	19
8	1.42	1.42	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Overgrown bamboo limits access to lower patrol road.	38.626930 ° -121.444191 °	38.626930 ° -121.444191 °	32 Y
9	1.53	1.53	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Cactus planted within 10-ft of levee toe. Storage building is also within 10-ft of the toe.	38.627742 ° -121.442524 °	38.627742 ° -121.442524 °	2
10	1.54	1.54	Earthen Levee	Encroachments	LS	CO	Buildings Inspector Comments: Large side building is within 10-ft of the levee toe.	38.627744 ° -121.442367 °	38.627744 ° -121.442367 °	30
11	1.56	1.56	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence is within 10-ft of the levee toe.	38.627682 ° -121.442113 °	38.627682 ° -121.442113 °	3
12	1.56	1.56	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence is within 10-ft of the levee toe.	38.627707 ° -121.441965 °	38.627707 ° -121.441965 °	4 Y
13	1.59	1.59	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Privacy fence is within 10-ft of the levee toe.	38.627733 ° -121.441415 °	38.627733 ° -121.441415 °	29
14	1.60	1.60	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Privacy fence is within 10-ft of the levee toe.	38.627708 ° -121.441254 °	38.627708 ° -121.441254 °	28

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway					Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 07 Arcade Creek					Right	1.92	10/02/2009 11/03/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	
15	1.62	1.62	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Privacy fence and landscaping are within 10-ft of the levee toe. Photo	38.627681 ° -121.441021 °	38.627681 ° -121.441021 °	27 Y
16	1.62	1.62	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence is within 10-ft of the levee toe.	38.627663 ° -121.440784 °	38.627663 ° -121.440784 °	26 Y
17	1.64	1.64	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence is within 10-ft of the levee toe.	38.627679 ° -121.440582 °	38.627679 ° -121.440582 °	25 Y
18	1.65	1.65	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence is within 10-ft of the levee toe.	38.627620 ° -121.440467 °	38.627620 ° -121.440467 °	5 Y
19	1.68	1.68	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence with vines are within 10-ft of the levee toe.	38.627868 ° -121.439962 °	38.627868 ° -121.439962 °	6 Y
20	1.69	1.69	Earthen Levee	Encroachments	LS	CO	Buildings Inspector Comments: Corner of building protrudes into levee slope. Wooden fence is built on the levee slope.	38.627935 ° -121.439758 °	38.627935 ° -121.439758 °	7 Y
21	1.70	1.70	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Palm tree is completely obstructive.	38.628086 ° -121.439544 °	38.628086 ° -121.439544 °	24 Y
22	1.72	1.72	Earthen Levee	Encroachments	LS	CO	Buildings Inspector Comments: Levee slope is built around building corner. Property has a chain link privacy fence with barbed wire.	38.628102 ° -121.439283 °	38.628102 ° -121.439283 °	8 Y
23	1.73	1.73	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden fence and redwood trees are within 10-ft of levee toe.	38.628208 ° -121.439142 °	38.628208 ° -121.439142 °	23 Y
24	1.74	1.74	Earthen Levee	Encroachments	LS	CO	Fences Inspector Comments: Wooden privacy fence is within 10-ft of the levee toe.	38.628197 ° -121.438863 °	38.628197 ° -121.438863 °	9 Y
25	1.77	1.77	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Ivy and other landscape plantings have grown up chain link fence on the levee toe. Building is within 10-ft of the levee toe. Prunings are on the levee slope.	38.628273 ° -121.438255 °	38.628273 ° -121.438255 °	10 Y
26	1.79	1.79	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Dense ivy and landscaping planted on chain link fence on levee toe. Porch and awning are within 10-ft of the levee toe.	38.628297 ° -121.437995 °	38.628297 ° -121.437995 °	11 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway					Bank	Unit Miles	Inspection Start/End		Inspector
Unit No. 07 Arcade Creek					Right	1.92	10/02/2009 11/03/2009		John Paasch

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	
27	1.80	1.80	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Chain link privacy fence with barbed wire is within 10-ft of levee toe.	38.628307 ° -121.437842 °	38.628307 ° -121.437842 °	12
28	1.81	1.81	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Chain link privacy fence is within 10-ft of levee toe.	38.628303 ° -121.437693 °	38.628303 ° -121.437693 °	13
29	1.81	1.81	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Chain link privacy fence is within 10-ft of levee toe.	38.628303 ° -121.437530 °	38.628303 ° -121.437530 °	14 Y
30	1.83	1.83	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Photo: Dense ivy growing on chain link fence within 10-ft of levee toe.	38.628295 ° -121.437282 °	38.628295 ° -121.437282 °	15 Y
31	1.84	1.84	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: GreenBld: Dense ivy and trees along chain link fence on levee toe. Large building is within 10-ft of levee toe.	38.628262 ° -121.436985 °	38.628262 ° -121.436985 °	16 Y
32	1.85	1.85	Earthen Levee	Encroachments	LS	CO	Buildings Inspector Comments: Wooden shed and landscaping along chain link fence within 10-ft of levee toe.	38.628318 ° -121.436794 °	38.628318 ° -121.436794 °	22 Y
33	1.88	1.88	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: Wooden side building and juniper trees along chain link fence are within 10-ft of landside toe.	38.628280 ° -121.436365 °	38.628280 ° -121.436365 °	21 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 07 Arcade Creek	Right	1.92	10/02/2009 11/03/2009	John Paasch

Levee Mile Report Line	1
Start Levee Mile	0.04
End Levee Mile	0.53
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Excellent maintenance of landside slope and crown.	
jpaasch_20091104_164.jpg	



Levee Mile Report Line	2
Start Levee Mile	0.34
End Levee Mile	0.34
Location	Water Side
Category	Channels
Item	Vegetation & Obstructions
Beaver den in low flow channel.	
jpaasch_20091104_165.jpg	



Levee Mile Report Line	5
Start Levee Mile	0.72
End Levee Mile	1.22
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Ideal vegetation maintenance on crown and both slopes.	
jpaasch_20091104_163.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 07 Arcade Creek	Right	1.92	10/02/2009 11/03/2009	John Paasch

Levee Mile Report Line	8
Start Levee Mile	1.42
End Levee Mile	1.42
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Landscaping adjacent to lower levee patrol road obstructs visibility and access.	
jpaasch_20091104_162.jpg	



Levee Mile Report Line	12
Start Levee Mile	1.56
End Levee Mile	1.56
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Privacy fence within 10-ft of the levee toe obstructs visibility and access. Landscaping should be trimmed and prunings removed.	
jpaasch_20091104_161.jpg	



Levee Mile Report Line	15
Start Levee Mile	1.62
End Levee Mile	1.62
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Privacy fence and landscaping within 10-ft of the levee toe obstructs visibility and access.	
jpaasch_20091104_160.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 07 Arcade Creek	Right	1.92	10/02/2009 11/03/2009	John Paasch

Levee Mile Report Line	17
Start Levee Mile	1.64
End Levee Mile	1.64
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Privacy fence within 10-ft of the levee toe obstructs visibility and access.	
jpaasch_20091104_159.jpg	



Levee Mile Report Line	20
Start Levee Mile	1.69
End Levee Mile	1.69
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Privacy fence and building within 10-ft of the levee toe obstructs visibility and access.	
jpaasch_20091104_158.jpg	



Levee Mile Report Line	21
Start Levee Mile	1.70
End Levee Mile	1.70
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Palm tree within 10-ft of the levee toe obstructs visibility and access.	
jpaasch_20091104_157.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 07 Arcade Creek	Right	1.92	10/02/2009 11/03/2009	John Paasch

Levee Mile Report Line	22
Start Levee Mile	1.72
End Levee Mile	1.72
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Privacy fence and structure within 10-ft of the levee toe obstructs visibility and access.	
jpaasch_20091104_156.jpg	



Levee Mile Report Line	24
Start Levee Mile	1.74
End Levee Mile	1.74
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Privacy fence within 10-ft of the levee toe obstructs visibility and access.	
jpaasch_20091104_155.jpg	



Levee Mile Report Line	25
Start Levee Mile	1.77
End Levee Mile	1.77
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Landscaping within 10-ft of the levee toe obstructs visibility and access.	
jpaasch_20091104_154.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 07 Arcade Creek	Right	1.92	10/02/2009 11/03/2009	John Paasch

Levee Mile Report Line	26
Start Levee Mile	1.79
End Levee Mile	1.79
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Landscaping and fence within 10-ft of the levee toe obstruct access and visibility.	
jpaasch_20091104_153.jpg	



Levee Mile Report Line	29
Start Levee Mile	1.81
End Levee Mile	1.81
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Privacy fence within 10-ft of the levee toe obstructs visibility and access.	
jpaasch_20091104_152.jpg	



Levee Mile Report Line	30
Start Levee Mile	1.83
End Levee Mile	1.83
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Dense ivy and fence obstruct visibility and access.	
jpaasch_20091104_151.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 07 Arcade Creek	Right	1.92	10/02/2009 11/03/2009	John Paasch

Levee Mile Report Line	31
Start Levee Mile	1.84
End Levee Mile	1.84
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Building, fence and landscaping are within 10-ft of the levee toe.

jpaasch_20091104_150.jpg



Levee Mile Report Line	32
Start Levee Mile	1.85
End Levee Mile	1.85
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Wooden shed and landscape plantings are within 10-ft of the levee toe.

jpaasch_20091104_149.jpg



Levee Mile Report Line	33
Start Levee Mile	1.88
End Levee Mile	1.88
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Building, fence and trees are within 10-ft of levee toe.

jpaasch_20091104_148.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2009 Levee Inspection Results

American River Flood Control District

Waterway			Bank	Unit Miles
Unit No. 08 Magpie Creek Diversion			Left	1.43
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/17/2009		9/30/2009	
DWR Inspector	Clay Thomas		John Paasch	
Accompanied By			Ilene Wellman-Barbree	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector		
Unit No. 08 Magpie Creek Diversion				Left	1.43	10/02/2009 10/02/2009	John Paasch		

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.12	0.12	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows. Inspector Comments: Inactive rodent hole.	38.668370 ° -121.445331 °	38.668370 ° -121.445331 °	7
2	0.31	0.48	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Chain link fence near levee toe.	38.668191 ° -121.442059 °	38.668118 ° -121.438659 °	4 Y
3	0.31	0.48	Earthen Levee	Encroachments	WS	PO	Landscaping Inspector Comments: Re-vegetation site on levee slope.	38.668191 ° -121.442059 °	38.668116 ° -121.438661 °	5
4	0.43	0.43	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Vines on fence block visibility.	38.668141 ° -121.439755 °	38.668147 ° -121.440248 °	6
5	1.19	1.19	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Two fence posts and barbed wire are within 10' of the landside toe.	38.663688 ° -121.431677 °	38.663688 ° -121.431677 °	3
6	1.26	1.32	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Barbed wire fence runs along the levee toe.	38.662672 ° -121.431672 °	38.661823 ° -121.431678 °	2 Y
7	1.35	1.35	Earthen Levee	Encroachments	LS	M	Debris Inspector Comments: Rusty metal sheets located within landside drainage area.	38.661665 ° -121.431343 °	38.661665 ° -121.431343 °	1

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 08 Magpie Creek Diversion	Left	1.43	10/02/2009 10/02/2009	John Paasch

Levee Mile Report Line	2
Start Levee Mile	0.31
End Levee Mile	0.48
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Fence across from re-vegetation site limits accessibility.	
jpaasch_20091002_2.jpg	



Levee Mile Report Line	6
Start Levee Mile	1.26
End Levee Mile	1.32
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Barbed wire fence on levee toe.	
jpaasch_20091002_1.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2009 Levee Inspection Results

American River Flood Control District

Waterway			Bank	Unit Miles
Unit No. 09 American River			Right	4.32
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/17/2009		9/30/2009	
DWR Inspector	Clay Thomas		John Paasch	
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 09 American River						Right	4.32	09/30/2009 09/30/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	1.13	1.13	Earthen Levee	Encroachments	LS	PO	Landscaping	38.563040 ° -121.402168 °	38.563040 ° -121.402168 °	3
2	3.11	3.24	Earthen Levee	Encroachments	LS	CO	Fences	38.576423 ° -121.419117 °	38.578248 ° -121.418475 °	2
3	3.24	3.32	Earthen Levee	Encroachments	LS	PO	Fences	38.578258 ° -121.418475 °	38.579363 ° -121.418100 °	1

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2009 Levee Inspection Results

American River Flood Control District

Waterway			Bank	Unit Miles
Unit No. 10 American River			Right	3.34

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/17/2009		9/30/2009	
DWR Inspector	Clay Thomas		John Paasch	
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 10 American River						Right	3.34	09/30/2009 09/30/2009	John Paasch	

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	2.33	2.40	Earthen Levee	Animal Control	LS	C	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows. Inspector Comments: Burrows have been grouted since initial fall inspection.	38.576565 ° -121.354747 °	38.576032 ° -121.355892 °	3
2	2.75	2.75	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.573425 ° -121.361322 °	38.573425 ° -121.361322 °	2
3	3.90	3.90	Earthen Levee	Encroachments	LS	PO	Fences	38.568300 ° -121.380910 °	38.568300 ° -121.380910 °	1

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2009 Levee Inspection Results

American River Flood Control District

Waterway			Bank	Unit Miles
Unit No. 11 New Linda Creek			Left	0.73
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/17/2009		9/30/2009	
DWR Inspector	Clay Thomas		John Paasch	
Accompanied By			Ilene Wellman-Barbree	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

American River Flood Control District

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 11 New Linda Creek						Left	0.73	10/02/2009 10/02/2009	John Paasch	

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.21	0.21	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.663942 ° -121.454669 °	38.663942 ° -121.454669 °	3
2	0.35	0.35	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows. Inspector Comments: Inactive rodent holes near corrals.	38.665143 ° -121.452450 °	38.665143 ° -121.452450 °	1
3	0.35	0.35	Earthen Levee	Encroachments	LS	C	Pipe Inspector Comments: 40-ft long steel pipe along landside toe.	38.665144 ° -121.452450 °	38.665144 ° -121.452450 °	2

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected